

**DEPARTMENT OF TRANSPORTATION**

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch  
690 Walnut Ave.St. 150  
Vallejo, CA 94592-1133  
(707) 649-5453  
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-009720**Date Inspected:** 17-Oct-2009**Project Name:** SAS Superstructure**OSM Arrival Time:** 645**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1845**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Li zhi jiang**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG / TOWER**Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance (QA) Inspector, D.Sukanthan was present during the time noted above for observations relative to the work being performed.

**TOWER # NORTH TOWER LIFT 3 (OPEN YARD)**

This QA inspector performed Ultrasonic Test of approximately 10% of the area previously tested and accepted by ZPMC Quality Control Personnel. This QA Inspector generated an Ultrasonic Test report for this date. The member is identified as CD Corner stiffener. Inspection Notification number- 004414. The weld designations reviewed are as follows:

(NSTL3-3K/K-014,015,016,017,018,019,020,021,022,023,024,025,026)

(NSTL3-3K/K-038,039,040,041,042,043,044,045,046,047,048)

This QA Inspector randomly observed the following work in progress:

**OBG # CROSS BEAM 15 (BAY 1)****Flux Cored Arc Welding Process:**

Welding of weld joint -046 located on PCMK FB204-047. Welder is identified as 216575. ZPMC QC is identified as Tian lei. The welding variables recorded by QC appeared to comply with the WPS-345-FCAW-2G

---

## WELDING INSPECTION REPORT

( Continued Page 2 of 2 )

---

(2F)-Repair-1.

Welding of weld joint –009 located on PCMK FB205-048. Welder is identified as 219188. ZPMC QC is identified as Tian lei. The welding variables recorded by QC appeared to comply with the WPS-345-FCAW-2G (2F)-Repair-1.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

### Summary of Conversations:

No Relevant Conversation

### Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang 150-00422372, who represents the Office of Structural Materials for your project.

---

<b>Inspected By:</b>	Sukanthan,Dhanasingh	Quality Assurance Inspector
<b>Reviewed By:</b>	Hall,Steven	QA Reviewer

---